Release Notes—AJA Driver v10.4

Driver update for T-TAP™

General

This software is for the initial release of T-TAP™. If installing onto a computer that has previously had another video capture card or drivers, we recommend running the AJA Conflict Checker utility BEFORE installing this software. The AJA Conflict Checker will help you identify old drivers or software files that need to be removed before installing the new software.

Installation Notes—Please Read

Mac OS X 10.8 Gatekeeper

On Mountain Lion, ensure that the Security & Privacy settings are configured to allow applications downloaded from Mac App Store and identified developers, as shown.

New Features

- Support for AJA T-TAP™ Thunderbolt-enabled device added with this release.

T-TAP™ Notes

Although the AJA T-TAP™ supports "plug and play" functionality, many applications do not recognize or operate properly if an input/output device is removed while they are in use. AJA recommends that if the AJA T-TAP™ is ever removed while an application is in use, that you quit the application and then relaunch it after the AJA T-TAP™ is reconnected.

Relevant Products

The following products are covered by this update:

- T-TAP™

AJA
VIDEO SYSTEMS