Ki Pro Ultra Release Notes – v2.2

Firmware update for Ki Pro Ultra v2.2

Introduction

This firmware update is a major new feature release for Ki Pro Ultra. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.`

New Features

MXF with OP1A support for DNxHD encoded files has been introduced, bringing true Avid MXF compatibility for HD workflows with the following profile support:

- DNxHD HQ (220x)
- DNxHD SQ (145)
- DNxHD LB (36)

Enhancements

Minor bug fixes and various improvements have been made, including:

- Improved interlace video support for clips that have been exported from Avid Media Composer
- Enhanced support for Firefox on Windows
- Quicktime Files exported with FCPX chapter markers are now supported
- General disk performance improvements

Note:

KPU v2.2 may cause potential Ki Pro Ultra playback incompatibility with NLE exported video files that have a stereo audio track. By exporting video files with channels 1 and 2 set to mono, this issue can be avoided. A point update to v2.2 will be released to address this issue soon.

Firmware Update Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.

- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.

- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com   Phone: +1-530-271-3190   Fax: +1-530-274-9442

Web: www.aja.com/support   Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA