

Ki Pro Ultra Release Notes – v2.0

Firmware update for Ki Pro Ultra v2.0

Introduction

This firmware update is a major new feature release for Ki Pro Ultra. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

New Features

Avid DNxHD .MOV encoding and decoding support for the following profile, frame sizes and rates:

- DNxHD HQX (220x)
- DNxHD SQ (145)
- DNxHD LB (36)
- 1080p 23.98, 24, 25, 29.97
- 1080i 25, 29.97
- 1080PsF 23.98, 24, 25, 29.97
- 720p 50, 59.94

Enhancements

Minor bug fixes and various improvements have been made, including:

- Timecode superimposition is now correctly displayed.
- Loop playback functions correctly when control is set to 'RS-422 Only'.
- Genlock mismatch error prompt has been removed.
- Record Minutes feature works as defined in the manual.
- Clip Playback compatibility improved.

Firmware Update Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com Phone: +1-530-271-3190 Fax: +1-530-274-9442

Web: www.aja.com/support Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA