

AJA Mini-Config v2.26.13 - Release Notes

Mini-Config v2.26.13 Software

Introduction

Mini-Config v2.26.13 software is a maintenance release that includes bug fixes for the HA5-12G, Hi5-Fiber, Hi5-Plus, Hi5-4K-Plus and the V2Digital. Please carefully review the release notes to check which AJA Mini-Converters have new features and fixes. It is highly recommended that you update the firmware to avoid any potential issues.

Be sure to consult the Installation and Operation Guide (User Manual) for detailed information about features and configuration guidelines. The most current documentation can always be found on the [Mini-Config Support Page](#).

Products Supported in This Release

3G-AM	12G-AMA-R	HA5-4K	Hi5-12G-R-ST	ROI
3G-AMA	12G-AMA-R-ST	HA5-Fiber	Hi5-12G-TR	ROI-DP
4K2HD	12G-AMA-T	HA5-Plus	Hi5-3D	ROI-DVI
12G-AM	12G-AMA-T-ST	HB-R-SDI	Hi5-3G	ROI-HDMI
12G-AM-R	12G-AMA-TR	HB-T-SDI	Hi5-4K	ROI-SDI
12G-AM-R-ST	12GM	HD10MD4	Hi5-4K-Plus	RovoRx-SDI
12G-AM-T	FS-Mini	HDP2	Hi5-Fiber	UDC
12G-AM-T-ST	HA5-12G	HDP3	Hi5-Plus	V2Analog
12G-AM-TR	HA5-12G-T	Hi5-12G	LUT-box	V2Digital
12G-AMA	HA5-12G-T-ST	Hi5-12G-R	OG-3G-AM	

Fixes, Changes, and Improvements in v2.26.13

HA5-12G (v1.12)

- Fixes an issue where the audio output was muted when the Frame Rate option was selected to change the output from Fractional to Integer or Integer to Fractional or when setting genlock to Free Run.

Hi5-Fiber (v2.4)

- Fixes an issue where PsF inputs and audio would not work after prolonged periods with no input signal after power cycling.

Hi5-Plus (v1.9)

- Fixes an issue where PsF inputs and audio would not work after prolonged periods with no input signal after power cycling.

Hi5-4K-Plus (v1.18)

- Fixes an issue where some auto settings were not working properly by restoring the firmware version to the same as version 1.16.
- Fixes an issue where the Hi5-4K-Plus v1.17 did not properly emit HDR metadata

V2Digital (v2.7)

- Fixes an issue where the device intermittently will configure as composite instead of S-Video on power-up.
- Fixes an issue where the analog input will not configure as S-Video using SW-3 dip switch when in local mode.

Installing the Latest Software

Mini-Converters come from the factory with the most current version of firmware pre-installed. To get the latest version of Mini-Config, visit the AJA website:

<https://www.aja.com/products/mini-config-software>

The Mini-Config software can also be found on the Downloads tab on the Mini-Converter's webpage. Previous releases of the AJA Mini-Config software are also available in the Software Archive section for each supported Mini-Converter.

Firmware Upgrade Procedure

The manual available under the support listings for your AJA Mini-Converter describes the firmware update process; please refer to it to properly update your firmware. Product manuals are also installed with the software in the /AJA/Mini-Config/Documentation folder.

Individual product manuals are available online for download from the individual Mini-Converter's webpage which can be reached by selecting the desired converter on our support page. <http://www.aja.com/support>.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: <https://www.aja.com/support/contact>

Shipping: 180 Litton Dr. Grass Valley, CA 95945, USA