

Release Notes - XENA Version 3.0.1



General

If you are installing for the first time please read the “ReadMeFirst.PDF” located on the installation CD. This software release adds new features and improves functionality of the XENA LS/LSe, HS, LH/LHe, and 2K/2Ke cards from AJA.

Requirements

- QuickTime™ 7.1.3 or higher must be installed on the workstation for proper XENA operation.
- Operating Systems Required: Windows XP (32-Bit) or Windows Vista (32-Bit) (Business, or Ultimate)

New Features

- New 1.2 Pixel Aspect Ratio option added to the XENA 486i editing mode in Premiere Pro

Resolved Issues

- XENA installer now correctly installs the plug-in on the Japanese version of Photoshop CS3
- XENA CS3 File importer no longer interferes with wav file importing in Adobe Encore CS3
- Use of incorrect Adobe font in Premiere Pro CS3 has been fixed
- Problems with audio playback in the source monitor of Premiere Pro CS3 have been fixed
- Incorrect assignment of SDI outputs when using secondary format conversion has been fixed.

Known Issues

- Time code is not stored in crash captured clips when the time code source is RS-422. If this is required, use embedded time code instead of RS-422 time code.
- Jog functionality may behave abnormally with some Sony decks.
- Capture settings in Premiere Pro cannot be changed unless the capture window is open. Attempting to open the capture settings panel from either the batch capture override dialog, or from the general project settings dialog will cause the capture settings options to be locked. Press F5 to launch the Premiere Pro capture window, and alter the AJA capture settings from here.
- AJA Real-Time cropping effects in Premiere Pro are not supported for sequential file formats written bottom to top. Rendering will be required.
- In Premiere Pro playback settings, checking or un-checking “render RT files of different resolutions” will not take effect immediately. To workaround, save project, close project, and then reopen it. The new settings will take effect.
- Variable frame rates (VFR) with pull down added are not adjusted for time code.
- *Crash capture* and *Print to Video* will work on pull down frame rates, but insert edit, in/out capture, and batch capture, will not.



Web: www.aja.com Phone: 530.274.2048 Fax: 530.274.9442 Web: www.aja.com Phone: 530.274.2048 Fax: 530.274.9442