AJA Mac Drivers Release Notes—v10.4.1

Drivers for KONA and lo products

General

This driver version is compatible with Mac OS X 10.7 (Lion) and OS X 10.8 (Mountain Lion).

If installing onto a computer that has previously had another video capture card or drivers installed, we recommend running the AJA Conflict Checker utility BEFORE installing the software.


The AJA Conflict Checker will help you identify old drivers or software files that need to be removed before installing the new software.

Also, please read the "ReadMeFirst.PDF" document, particularly if installing for the first time.

Installation Notes—Please Read

Mac OS X 10.8 Gatekeeper

On Mountain Lion, ensure that the Security & Privacy settings are configured to allow applications downloaded from Mac App Store and identified developers, as shown.



Improvements

- All: Increased range of H&V timing controls
- T-TAP: Fixed a problem where Channel 8 audio was being duplicated on channels 9-16.
- T-TAP: Fixed a problem with incorrect behavior when the Thunderbolt cable was pulled during playback.
- KONA LHe Plus: Fixed a problem with captures when VANC was enabled.
- loXT: Fixed an analog audio out problem where L&R channels were swapped.



Relevant Products

The following products are covered by this update:

KONA 3G KONA LHe Plus

KONA 3 lo Express

KONA LHi lo XT