

Release Notes - v1.2.1 Firmware

Requirements and Recommendations

This firmware version is uploaded to the AJA CION camera via the built-in web UI.

Note: AJA recommends performing a Factory Reset under the CONFIG menu **prior to performing the firmware update and then again **after** the firmware update has been installed.**

For detailed instructions on configuring the web UI and updating the CION firmware, as well as operation of new features, please refer to the CION Production Camera Operations Manual.

You can download the CION manual from the AJA Support website:

<https://www.aja.com/products/cion#support>

Improvements

- Resolved an issue where, under certain conditions, the Gamma selection was not being properly restored when going from RECORD to PLAYBACK then back to RECORD
- Resolved a field alignment issue when operating in 1080p-60 3G-B
- Resolved an issue with the Video Signal Generator being affected by the saturation setting
- Other fixes to enhance encoding stability