

# Ki Pro Ultra Release Notes – v1.3

## Firmware update for Ki Pro Ultra v1.3

### Introduction

---

This firmware update is a maintenance release for Ki Pro Ultra. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of [www.aja.com](http://www.aja.com).

### New Features

---

- 4K/UltraHD PsF recording and playback has now been added with support for :
  - 4K as 23.98/24/25/29.97 PsF 10-bit 422 YCbCr
  - UltraHD as 23.98/24/25/29.97 PsF 10-bit 422 YCbCr
  - Allows Square Division (SQD) input as 4 x 1.5G-SDI only
- Timecode has now been added to the monitor output of Ki Pro Ultra

### Enhancements

---

Minor bug fixes and various improvements have been made, including:

- Timeout between HTTP socket disconnection has been improved to allow longer connections without interruption.
- Media detection and selection has been enhanced
- HDMI performance has been improved

## Firmware Update Considerations

---

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

## Technical Support

---

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: [support@aja.com](mailto:support@aja.com)

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: [www.aja.com/support](http://www.aja.com/support)

Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA