

# Ki Pro Ultra Release Notes – v2.1

## Firmware update for Ki Pro Ultra v2.1

### Introduction

---

This firmware update is a major new feature release for Ki Pro Ultra. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of [www.aja.com](http://www.aja.com).

### New Features

---

Additional Avid DNxHD .MOV encoding and decoding support for the following profile, frame sizes and rates:

- DNxHD HQX (220x)
- DNxHD SQ (145)
- DNxHD LB (36)
- 1080p 50, 59.94

### Enhancements

---

Minor bug fixes and various improvements have been made, including:

- Added playback support for exported ProRes files from Apple Final Cut Pro v.10.3
- LPCM audio support has been improved.
- Simple Time Code read has been added to the API/REST interface.
- Output timing corrected for all Apple ProRes and Avid DNxHD playback formats.

## Firmware Update Considerations

---

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

## Technical Support

---

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: [support@aja.com](mailto:support@aja.com) Phone: +1-530-271-3190 Fax: +1-530-274-9442

Web: [www.aja.com/support](http://www.aja.com/support) Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA