

AJA Mini-Config v2.27.1 - Release Notes

Mini-Config v2.27.1 Software

Introduction

Mini-Config v2.27.1 software release includes a new feature for the 12G-AM and 12G-AMA, and various bug fixes for other Mini-Converters. Please carefully review the release notes to check which AJA Mini-Converters have new features and fixes. It is highly recommended that you update to the latest firmware to avoid any potential issues.

Be sure to consult the Installation and Operation Guide (User Manual) for detailed information about features and configuration guidelines. The most current documentation can always be found on the [Mini-Config Support Page](#).

Products Supported in This Release

3G-AM	12G-AMA-R	HA5-4K	Hi5-12G-R-ST	ROI
3G-AMA	12G-AMA-R-ST	HA5-Fiber	Hi5-12G-TR	ROI-DP
4K2HD	12G-AMA-T	HA5-Plus	Hi5-3D	ROI-DVI
12G-AM	12G-AMA-T-ST	HB-R-SDI	Hi5-3G	ROI-HDMI
12G-AM-R	12G-AMA-TR	HB-T-SDI	Hi5-4K	ROI-SDI
12G-AM-R-ST	12GM	HD10MD4	Hi5-4K-Plus	RovoRx-SDI
12G-AM-T	FS-Mini	HDP2	Hi5-Fiber	UDC
12G-AM-T-ST	HA5-12G	HDP3	Hi5-Plus	UDC-4K
12G-AM-TR	HA5-12G-T	Hi5-12G	LUT-box	V2Analog
12G-AMA	HA5-12G-T-ST	Hi5-12G-R	OG-3G-AMA	V2Digital

Fixes, Changes, and Improvements in v2.27.1

12G-AM (v1.5)

- Auto Switch Over feature added gives the option to automatically select between the SDI input and the Optical input.
- Fixes an issue where the 3G-B signals are incorrectly identified as interlaced/PsF.
- Fixes an issue where SDI input is required when feeding fiber to the SFP for audio output to work.

12G-AMA (v1.5)

- Auto Switch Over feature added gives the option to automatically select between the SDI input and the Optical input.
- Fixes an issue where 3G-B signals are incorrectly identified as interlaced/PsF.

HA5-12G (v1.13)

- Fixes an issue where some graphics cards are causing the SDI Output to intermittently reset.

HA5-4K (v1.18)

- Fixes an issue where reverting to Factory Defaults and recall Presets won't recall the 3G-SDI Mode setting if it is set to 2x 1.5G-SDI on HA5-4K.

Hi5-12G (v1.18)

- Fixes an issue where HDMI output is sometimes configured as 1080p when relocking to a 1080i source.

ROI-DP (v1.8)

- Prevents an issue where some parameters can no longer be set and the unit becomes non-functional. Customers experiencing this issue should contact AJA Technical Support.

ROI-DVI (v1.8)

- Prevents an issue where some parameters can no longer be set and the unit becomes non-functional. Customers experiencing this issue should contact AJA Technical Support.

ROI-HDMI (v1.8)

- Prevents an issue where some parameters can no longer be set and the unit becomes non-functional. Customers experiencing this issue should contact AJA Technical Support.

ROI-SDI (v1.4)

- Prevents an issue where some parameters can no longer be set and the unit becomes non-functional. Customers experiencing this issue should contact AJA Technical Support.

ROI (v2.5)

- Prevents an issue where some parameters can no longer be set and the unit becomes non-functional. Customers experiencing this issue should contact AJA Technical Support.

UDC-4K (v1.4)

- Improves handling of HDMI AVI Infoframe changes.
- For SDI and HDMI inputs, Audio SRC settings are now On by default.
- System Genlock Auto setting no longer attempts to lock to the HDMI Input. System Genlock can still be manually set to HDMI Input.

Installing the Latest Software

To get the latest version of Mini-Config, visit the AJA website:

<https://www.aja.com/products/mini-config-software>

The Mini-Config software can also be found on the Downloads tab on the Mini-Converter's webpage. Previous releases of the AJA Mini-Config software are also available in the Software Archive section for each supported Mini-Converter.

Firmware Upgrade Procedure

The manual available under the support listings for your AJA Mini-Converter describes the firmware update process; please refer to it to properly update your firmware. Product manuals are also installed with the software in the /AJA/Mini-Config/Documentation folder.

Individual product manuals are available online for download from the individual Mini-Converter's webpage which can be reached by selecting the desired converter on our support page. <http://www.aja.com/support>.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com

Phone: +1-530-271-3190

Fax: +1-530-274-9442

Web: <https://www.aja.com/support/contact>

Shipping: 180 Litton Dr. Grass Valley, CA 95945, USA