

Ki Pro Rack Release Notes - v5.1.0.3

Firmware update for Ki Pro Rack

Introduction

This firmware update is a maintenance release for Ki Pro Rack. Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

Improvements

- Addressed an issue where time code associated with drop frame (DF) recordings is reported incorrectly during playback. Recordings are not affected, incorrect time code reporting would only occur during playback. This has been fixed in Maintenance Release 5.1.0.3
- Minor performance improvements.

Firmware Update Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Some clips created by Ki Pro Rack may cause Final Cut Pro 7 to bring up a "not optimized" prompt when imported. These clips are valid and can be used within Final Cut Pro 7.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.