

Ki Pro Ultra Release Notes – v3.1

Firmware update for Ki Pro Ultra v3.1

Introduction

This firmware update is a maintenance release for Ki Pro Ultra.

Be sure to consult the Installation and Operation Guide (user manual) for detailed information about features and configuration guidelines. The most current documentation can always be found in the Support section of www.aja.com.

Enhancements

Minor bug fixes and various improvements have been made, including:

- Added ability to set playback speed setting in REST.
- Loss Of Video support has been improved for situations where vulnerabilities were previously discovered.

Firmware Update Considerations

- AJA recommends a Factory Reset under the CONFIG menu prior to updating firmware.
- After a firmware update, the web browser (Safari, Firefox, etc.) may lose its connection. A refresh of the web browser will reconnect the web UI.
- Do not attempt firmware updates while recording is in progress. Be sure the device is in the stopped state before performing a firmware update.

Technical Support

AJA Technical Support is free and available to help you answer questions or resolve issues with any of your AJA products.

To contact AJA Technical Support:

Email: support@aja.com Phone: +1-530-271-3190 Fax: +1-530-274-9442

Web: www.aja.com/support Shipping: 180 Litton Dr. Grass Valley, CA 95945 USA